


**LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: April 26, 2007


TECHNICIAN NAME: Baltazar

TECHNICIAN SIGNATURE 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2nd Rdg.	3 rd Rdg.	1 st Rdg.	2nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.25	1237	1243	19.77	19.77	19.77	21.81	21.81	21.81				
LC-2	21.90	21.89	1250	1301	13.19	13.19	13.19	21.21	21.21	21.21				
LC-3	22.20													
LC-4	21.90	21.90	1311	1324	12.85	12.85	12.85	21.17	21.17	21.17				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\Febuary2007\Feb107LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Baltazar		12 21	April 26, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK		OK		✓✓✓
Well Casing and Cap/Plug	OK	OK		OK		✓✓✓
Liquid Present in Well Box	NO	NO		NO		✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollection\Wells\WorkPlan+FieldForms\February2007\Feb107LC-WellsInspection(YF).doc

